Town of Kernersville Safety and Health
Policy and Procedure Manual

Lockout Tagout Section 0090

Date 10/99

Revised 07/22

I. Standard

NCOSHA Standard for General Industry 1910.147--Control of Hazardous Energy Sources (Lockout/Tagout).

.

II. Introduction

There are many hazardous energy sources which must be properly controlled to prevent potential serious injuries to those performing servicing and maintenance of equipment, machines, and systems. Hazardous energy which may injure employees must be controlled by following standard Lockout/Tagout (LOTO) procedures.

III. Identified Tasks

Town of Kernersville employees do not perform tasks dealing with the shutdown of machines and the danger of hazardous energy sources. Therefore, the Town of Kernersville does not have a detailed LOTO policy. Town of Kernersville employees have been trained to follow best practices for tagging out damage or non-working tools or equipment. However, these tasks do not require locking out any machines with hazardous energy. See also the Solid Waste Division's LOTO for vehicles, Central Maintenance LOTO for vehicle lifts, Town Hall LOTO for boilers, Public Services LOTO for boilers.